Monday, 22/12/2008 8:31:55 AM

Linda Lacelle **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services Drawing Name : LUG ASSEMBLY 206L/407 GHW LUG Job Number : 44217 **Estimate Number** : 10318 P.O. Number Part Number : D2659 This Issue : 22/12/2008 S.O. No. : **Drawing Number** : D2659 REV A Prsht Rev. : NC **Project Number** : N/A First Issue : 11 : PURCHASED PARTS Type **Drawing Revision** : A : 43885 **Previous Run** Material Written By **Due Date** : 29/12/2008 Qty: 16 Um: Each Checked & Approved By Comment : Est: D 02.09.20 Re-format; Incorporated D2657; D2658 KJ/RF **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: D2657 Lug conputer Comment: Qty.: 1.0000 Each(s)/Unit Total: 16.0000 Each(s) Luq 2.0 D2658 Comment: Qty.: 1.0000 Each(s)/Unit Total: 16.0000 Each(s) Lug Assembly R43885 3.0 LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** 1-Weld as per Dwg D2659 using location Jig DT8208 A/RSteel Rod 1/08350 4.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 5.0 QC5 INSPECT WORK TO CURRENT STEE 812-22 Comment: INSPECT WORK TO CURRENT STEP 6.0 SPRAY PAINTING Comment: -PRIME GREY

Page 1

-SPRAY PAINT DELFLEET BLUE

-CLEAR DELFLEET

Form: rprocess

08-12 22

25

16

Dart Aerospace Ltd

W/O:		WORK ORDER C	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	!	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	 		1					
			-					
Part No	:	PAR #: Fault Category:	NC	R: Yes	No DQ	A :	Date: _	

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Verification Section C	Approval Chief Eng	Approval QC Inspector					
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date								
				1				!			
				; !							
		W.									
						·					
				i (
;											
				i ·							

NOTE: Date & initial all entries

Monday, 22/12/2008 8:31:55 AM Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LUG ASSEMBLY 206L/407 GHW LUG

Job Number: 44217

Part Number: D2659

Description:

Job Number:



Seq. #:

Machine Or Operation:

7.0

QC14

INSPECT SPRAY PAINT

. 4 . 10





Comment: INSPECT SPRAY PAINT

8.0

9.0

PACKAGING 1

PACKAGING RESOURCE #1



16

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 05-12-24

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES				····	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #- Fault Category: No		es No DO	۸۰	Date:	

NCR: DATE STEP Description of NC Section A		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	Verification	Ammanyal	A			
		Initial Action Description Sign & Chief Eng Chief Eng Date		Section C	Approval Chief Eng	Approval QC Inspector				
				1 1 1						
				i						
				; !						
				<u>i</u> 						
							15			


NOTE: Date & initial all entries




-0.312

Ŧ

DESIG	ng	DRAWN BY	DART AEROSPACE VICTORIA INTERNATIONAL AIRPORT,	
CHEC	€ D	APPROVED	DRAWING NO.	REV. A
,	<i>p</i> -	10	D2659	SHEET 1 OF 1
DATE			TITLE	SCALE
97.1	1.03		LUG ASSEMBLY	NTS
Α		97.11.03	NEW ISSUE	





WELD PER DART QSI 004 FINISH: POWDER COAT PER DART QSI 005 4.4 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED PART IS SYMMETRIC ABOUT CENTRE—LINES (ϕ)

ELEASE)